

Care instructions

smoothing cement, finished



brief instructions

procedure	product	remarks
<i>primary care</i>	LOBA® FloorCare	For shiny substrates
	LOBA® FloorCare Matt	For mat substrates
<i>maintenance</i>	LOBA® Cleaner	Maintenance cleaning
	LOBA® FloorCare	Maintenance care (shiny)
	LOBA® FloorCare Matt	Maintenance care (mat)
<i>stripping</i>	LOBA® CareRemover	-

First cleaning	Depending on soiling use LOBA® Cleaner or LOBA® CareRemover.
primary care	<p><i>pre-treatment</i></p> <p>The floor must be clean and free from grease, wax residues, etc. Old care layers must be removed. So at least a maintenance cleaning procedure using LOBA® Cleaner is necessary. In some cases a stripping procedure (see there) must be carried out.</p> <p>To primary care use LOBA® FloorCare (shiny) or LOBA® FloorCare Matt. Apply the appropriate care product in one layer using the LOBATool Wischwiesel. Avoid puddle formation. Never work into the drying film. After about 30 minutes the floor can be used again. Full stressability is achieved after drying over night.</p> <p>Caution: Shake well mat care products before use.</p>
maintenance	<p><i>cleaning</i></p> <p>Add 50-100mL LOBA® Cleaner to a bucket (10L) of water and wipe the floor. The cleaning intervals are to be determined according to practical experiences.</p> <p><i>caring</i></p> <p>If the existing protective layer is severely worn, a maintenance caring procedure can become necessary. To do so the floor has to be cleaned. Subsequently on shiny substrates LOBA® FloorCare, on mat substrates LOBA® FloorCare Matt has to be applied undiluted using the LOBATool Wischwiesel.</p> <p>Caution: To not unnecessarily render a stripping procedure more difficult, a build-up of more than 3 layers should be avoided.</p>
stripping	<p>A mechanical or manual stripping procedure becomes necessary if the floor shows strong soiling which can not be removed by common maintenance cleaning. A stripping procedure is also necessary if already 3 care layers are built up and the floor should be cared again.</p> <p>A stripping procedure is carried out using LOBA® CareRemover (1-2,5L to a bucket (10L) of water). Spread the cleaning solution onto the floor, allow to take effect for a short period of time and work over with a buffing machine and a green pad. On small areas also a scrubber can be used. Remove dissolved dirt before it dries again. Wipe afterwards with clean water to remove any cleaner residues.</p>
notes	<p>Stripping procedures should be carried out as seldom as possible.</p> <p>Mat care products are exclusively to be used on mat surfaces.</p>

Care instructions

smoothing cement, finished



At prolonged contact of plastifier-containing materials (e.g. rubber, plastics in stands of devices and furniture) with the varnish, plastifier-movement must be expected. This may cause non-reversible colorization of the varnish.

This bulletin can only be considered as recommendation without obligation. On account of the wide variety of conditions in practice, this information is not binding and does not warrant a contractual legal relationship or accessory obligations.